TO BE FILLED BY THE INSPECTING OFFICER

(Assistant Engineer)

Name of the school : M.E.S CENTRAL SCHOOL P.B No.22,Valanchery-676552,Malappuram DIST

1. Name of the officer : SUBASH.K.R

2. Location : LID&EW SectionValancheryMunicipality,Malappuram

3.Period for which the certificate is issued : 2023-2024

4.Type of buildings :

Building NO.1

GF) 6.20 X 6.19 X 3.90 X – Class room - 6 Nos

Do 6.66 x 6.19 x3.90 - Class room - 1 Nos

Do 7.66 x6.19 x3.90 –staff room- 1 Nos

Do 3.66 X5.71X 3.90-Sports room -1

Do 12.71 x 6.19 x3.90 – Lab-1Nos

Do 8.96 x 6.26 x 3.90 - Lab-1Nos

Do 9.21 x 6.26 x 3.90 – lab-1 Nos

Do FF)6.20X6.19 X3.85 Class room - 4 Nos

Do 6.66 X6.19X 3.85 Class room - 1 Nos

Do 7.66 X6.19 X 3.85 - staff room- 1 Nos

Do 3.66 X5.71X 3.85 Store room-1Nos

Do 6.23 x 6.19 x 3.85 – office room -1 No Ds

Do 12.71 x 6.19 x 3.85 – Lab – 1Nos

Do 8.96 x 6.26 x 3.85 – office room – 1 Nos

Do 9.21 x 6.26 x 3.85 – office room -1 Nos

SF) 6.20X 6.19X X3.82- Class room - 6 Nos

Do 6.30X6.19X3.82- Class room - 1 Nos

Do 6.66 X 6.19 X 3.82- Class room - 1 Nos

Do 7.66 X 6.19X 3.82 - Class room - 1 Nos

Do 3.66X 5.71X 3.82 - Class room - 1 Nos

Do 6.20X 6.19X3.82-– office room -1 No

Do 23.80X6.95X3.83- Library-1Nos

2) Building NO.2

GF) 15.00X 6.10X3.75- - Class room - 2 Nos

DO 5.25 X6.10X 3.75- staff room- 1 No

FF) 16.00 X 6.18 X 3.73 - Class room - 1 Nos

Do 11.50 x 6.25 x 3.73 – class room -1 nos

SF) 12.30 X 6.23 X 3.72 - class room -1 nos

Do 11.30 x 6.20 x 3.72 - class room -1 nos

3) Building NO.3

GF) 9.20 X 6.10 X 3.67 - class room -3 nos

FF) 9.20X 6.10 X 3.60- class room -3 nos

10.00 X6.10X3.60-- class room -1 nos

SF) 9.20X6.10X 3.60- class room -3 nos

6.08X 6.10X3.60- Lab-1Nos

5. Nature of defect if any :

a) foundation and basement: nill

b)superstructure : nill

c)doors and windows : nill

d) wood work wrought and put up: nill

e)Roof: nill

f)flooring : nill

g)miscellaneous : nill

6. Any major defect notices which will render the building unsafe if any manner: nill

7.whether maintenance work have been done properly :yes

8.whether structure is sound or not for conducting classes :yes,the structure is sound for conducting classes under normal wind and weather

Note: 1 The stability of the structure should be examined also with reference to location altitude intensity of wind ,explosure of flood etc

2.Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate

3.school compound shall be kept tidy and pest free. routine inspection inthis regard shall be done by the school authorities.

General note: This certificate issued will be subjected to scrutiny with the assessment register ofgramapanchayath, if any discrepancies are found this certificate shall stand void. unauthorized structures must be demolished or regularise.

Certified that the school was inspected by me on 23-05-2023 and found to be fit to conduct classes for the period 2023-2024 for the reason stated above

place: valanchery signature:

date: 23-5-23 Designation

Assistant Engineer
LSGD
Valanchery Municipality