

FITNESS CERTIFICATE
TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer)

Name of School : M.E.S CENTRAL SCHOOL.
(DR.N.K.Mohammed Memorial)

Name of officer : Shini. K R

1. Location : LID&EW Valanchery Municipality

2. Period for which certificate is issued : 2024-25

Types of building :

Building No:1

G.F)RCC : 6.20x6.19x3.90 -6 Class room
6.66x6.19x3.90- 1 Class room
7.66x6.19x3.90 - 1 Class room
3.66X5.71X3.90 Sports room
12.71x6.19x3.90 Lab
8.96x6.26X3.90 - Lab
9.21x6.26x3.90 - Lab

FIRST FLOOR

6.20X6.19X3.85 - 4 Class room
6.60x6.19x3.85 - 1 class room
7.66x6.19x3.85 - 1 Class room
3.66x5.71x3.85 - Store room
6.23x6.19x3.85 - Office room
12.71x6.19x3.85 - 1 Class room
8.96x6.20x3.85 - 1 Class room
9.21x6.26x3.85 Principal room
6.10x6.19x3.85 - manager room

SECOND FLOOR

6.20X6.19X3.85 - 6 Class room
6.66x6.19x3.85 - 1 Class room
6.23x6.19x3.85 - 1 class room
7.66x6.19x3.85 - 1 Class room
3.66x5.71x3.85 - 1 Class room
6.23x6.19x3.58 1 Class room
23.80 x6.95x3.85 Library

BUILDING NO:2

GF RCC) : 15x6.20x3.75 -2 Class room
5.4x4.95x3.75 Staff room 1Nos

First floor : 9.50x6.20x3.75 - 1 Class room
7.8x7.770x3.75 -1 Class room
11.80x6.20x3.75 1 Class room

Second floor: 13.20x6.20x3.75 - 2 Class room

BUILDING NO:3

GF RCC) : 9.20X6.10X3.60 - 3 Class room

First floor : 6.00x6.10x3.60 - office room
 9.20x6.10x3.60 - 3 Class room
 10.00x6.10x3.60 - 1 Class room
 Second floor : 9.20x6.10x3.60 - 3 Class room
 6.08x6.10x3.60 Computer lab

3. Nature of defects any
 a) Foundation and basement
 b) Superstructure
 c) Doors and windows
 d) Wood work and wrought and put up
 e) Roof
 f) Flooring
 g) Miscellaneous (cracks if any)



Nil

6. Any major defects noticed which will render the building unsafe in any manner : Not found at the time of inspection

7. Whether maintenance work have been done properly : Yes

8. Whether the structure is sound or not conducting classes normal : Sound for conducting classes under weather conditions

Note:

1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc
2. Any additional observation deemed for the certificate may be furnished separately with the certificate


CERTIFICATE

Certified that the school building was inspected by me on 26/06/2024 and found to be fit to conduct classes for the period 2024-25 with the following conditions.

Conditions:

1. Since the built-up area of this buildings is more than that of the assessment register of Gramma Panchayath, it should be regularised within six months in accordance with the law.
2. This fitness certificate is provisionally issued in this year only on the basis of previous year's fitness certificate.

Place : Valanchery
 Date : 29/06/2024



B. Shrinu
 29/06/24

**Assistant Engineer,
 (Full Additional Charge)
 Valanchery Municipality**